


# Upínač Weldon pro upínací stopky


## End mill holders



### Upínač Weldon DIN 6359 pro upínací stopky DIN 1835-B

For mounting straight-shank tools with lateral flat according to DIN 1835 form B (Weldon)



Název Catalog number	Kužel Taper	D	d	A		G 2,5 25.000 min <sup>-1</sup>
SK40.50.WE.06.AD	SK40	25	6	50	AD	•
SK40.50.WE.08.AD	SK40	28	8	50	AD	•
SK40.50.WE.10.AD	SK40	35	10	50	AD	•
SK40.50.WE.12.AD	SK40	42	12	50	AD	•
SK40.50.WE.14.AD	SK40	44	14	50	AD	•
SK40.63.WE.16.AD	SK40	48	16	63	AD	•
SK40.63.WE.18.AD	SK40	50	18	63	AD	•
SK40.63.WE.20.AD	SK40	52	20	63	AD	•
SK40.100.WE.25.AD	SK40	65	25	100	AD	•
SK40.100.WE.32.AD	SK40	72	32	100	AD	•
SK40.100.WE.06.AD	SK40	25	6	100	AD	•
SK40.100.WE.08.AD	SK40	28	8	100	AD	•
SK40.100.WE.10.AD	SK40	35	10	100	AD	•
SK40.100.WE.12.AD	SK40	42	12	100	AD	•
SK40.100.WE.14.AD	SK40	44	14	100	AD	•
SK40.100.WE.16.AD	SK40	48	16	100	AD	•
SK40.100.WE.18.AD	SK40	50	18	100	AD	•
SK40.100.WE.20.AD	SK40	52	20	100	AD	•

od průměr d = 25 se dvěma upínacími šrouby  
from d = 25 on two clamping screws


# Upínač Weldon pro upínací stopky


## End mill holders



### Upínač Weldon DIN 6359 pro upínací stopky DIN 1835-B

For mounting straight-shank tools with lateral flat according to DIN 1835 form B (Weldon)



Název Catalog number	Kužel Taper	D	d	A		G 2,5 25.000 min <sup>-1</sup>
SK40.35.WE.16.ADB	SK40	45	16	35	AD/B	•
SK40.35.WE.20.ADB	SK40	45	20	35	AD/B	•
SK40.35.WE.25.ADB	SK40	45	25	35	AD/B	•
SK40.65.WE.32.ADB	SK40	50	32	65	AD/B	•
SK40.50.WE.06.ADB	SK40	25	6	50	AD/B	•
SK40.50.WE.08.ADB	SK40	28	8	50	AD/B	•
SK40.50.WE.10.ADB	SK40	35	10	50	AD/B	•
SK40.50.WE.12.ADB	SK40	42	12	50	AD/B	•
SK40.50.WE.14.ADB	SK40	44	14	50	AD/B	•
SK40.63.WE.16.ADB	SK40	48	16	63	AD/B	•
SK40.63.WE.18.ADB	SK40	50	18	63	AD/B	•
SK40.63.WE.20.ADB	SK40	52	20	63	AD/B	•
SK40.100.WE.25.ADB	SK40	65	25	100	AD/B	•
SK40.100.WE.32.ADB	SK40	72	32	100	AD/B	•
SK40.120.WE.40.ADB	SK40	80	40	120	AD/B	•
SK40.100.WE.06.ADB	SK40	25	6	100	AD/B	•
SK40.100.WE.08.ADB	SK40	28	8	100	AD/B	•
SK40.100.WE.10.ADB	SK40	35	10	100	AD/B	•
SK40.100.WE.12.ADB	SK40	42	12	100	AD/B	•
SK40.100.WE.14.ADB	SK40	44	14	100	AD/B	•
SK40.100.WE.16.ADB	SK40	48	16	100	AD/B	•
SK40.100.WE.18.ADB	SK40	50	18	100	AD/B	•
SK40.100.WE.20.ADB	SK40	52	20	100	AD/B	•
SK40.130.WE.06.ADB	SK40	25	6	130	AD/B	•
SK40.130.WE.08.ADB	SK40	28	8	130	AD/B	•
SK40.130.WE.10.ADB	SK40	35	10	130	AD/B	•
SK40.130.WE.12.ADB	SK40	42	12	130	AD/B	•
SK40.130.WE.14.ADB	SK40	44	14	130	AD/B	•
SK40.130.WE.16.ADB	SK40	48	16	130	AD/B	•
SK40.130.WE.18.ADB	SK40	50	18	130	AD/B	•
SK40.130.WE.20.ADB	SK40	52	20	130	AD/B	•
SK40.160.WE.06.ADB	SK40	25	6	160	AD/B	•
SK40.160.WE.08.ADB	SK40	28	8	160	AD/B	•
SK40.160.WE.10.ADB	SK40	35	10	160	AD/B	•
SK40.160.WE.12.ADB	SK40	42	12	160	AD/B	•
SK40.160.WE.14.ADB	SK40	44	14	160	AD/B	•
SK40.160.WE.16.ADB	SK40	48	16	160	AD/B	•
SK40.160.WE.18.ADB	SK40	50	18	160	AD/B	•
SK40.160.WE.20.ADB	SK40	52	20	160	AD/B	•
SK40.160.WE.25.ADB	SK40	65	25	160	AD/B	•
SK40.160.WE.32.ADB	SK40	72	32	160	AD/B	•
SK40.160.WE.40.ADB	SK40	80	40	160	AD/B	•

od průměr d = 25 se dvěma upínacími šrouby

from d = 25 on two clamping screws


# Upínač Weldon pro upínací stopky


## End mill holders



### Upínač Weldon DIN 6359 pro upínací stopky DIN 1835-B

For mounting straight-shank tools with lateral flat according to DIN 1835 form B (Weldon)



Název Catalog number	Kužel Taper	D	d	A		G 2,5 25.000 min <sup>-1</sup>
SK50.63.WE.06.ADB	SK50	25	6	63	AD/B	•
SK50.63.WE.08.ADB	SK50	28	8	63	AD/B	•
SK50.63.WE.10.ADB	SK50	35	10	63	AD/B	•
SK50.63.WE.12.ADB	SK50	42	12	63	AD/B	•
SK50.63.WE.14.ADB	SK50	44	14	63	AD/B	•
SK50.63.WE.16.ADB	SK50	48	16	63	AD/B	•
SK50.63.WE.18.ADB	SK50	50	18	63	AD/B	•
SK50.63.WE.20.ADB	SK50	52	20	63	AD/B	•
SK50.80.WE.25.ADB	SK50	65	25	80	AD/B	•
SK50.100.WE.32.ADB	SK50	72	32	100	AD/B	•
SK50.100.WE.40.ADB	SK50	80	40	100	AD/B	•
SK50.120.WE.50.ADB	SK50	99	50	120	AD/B	•
SK50.100.WE.06.ADB	SK50	25	6	100	AD/B	•
SK50.100.WE.08.ADB	SK50	28	8	100	AD/B	•
SK50.100.WE.10.ADB	SK50	35	10	100	AD/B	•
SK50.100.WE.12.ADB	SK50	42	12	100	AD/B	•
SK50.100.WE.14.ADB	SK50	44	14	100	AD/B	•
SK50.100.WE.16.ADB	SK50	48	16	100	AD/B	•
SK50.100.WE.18.ADB	SK50	50	18	100	AD/B	•
SK50.100.WE.20.ADB	SK50	52	20	100	AD/B	•
SK50.120.WE.25.ADB	SK50	65	25	120	AD/B	•
SK50.130.WE.06.ADB	SK50	25	6	130	AD/B	•
SK50.130.WE.08.ADB	SK50	28	8	130	AD/B	•
SK50.130.WE.10.ADB	SK50	35	10	130	AD/B	•
SK50.130.WE.12.ADB	SK50	42	12	130	AD/B	•
SK50.130.WE.14.ADB	SK50	44	14	130	AD/B	•
SK50.130.WE.16.ADB	SK50	48	16	130	AD/B	•
SK50.130.WE.18.ADB	SK50	50	18	130	AD/B	•
SK50.130.WE.20.ADB	SK50	52	20	130	AD/B	•

od průměr d = 25 se dvěma upínacími šrouby

from d = 25 on two clamping screws


# Upínač Weldon pro upínací stopky


## End mill holders



### Upínač Weldon DIN 6359 pro upínací stopky DIN 1835-B

For mounting straight-shank tools with lateral flat according to DIN 1835 form B (Weldon)



Název Catalog number	Kužel Taper	D	d	A		G 2,5 25.000 min <sup>-1</sup>
SK50.160.WE.06.ADB	SK50	25	6	160	AD/B	•
SK50.160.WE.08.ADB	SK50	28	8	160	AD/B	•
SK50.160.WE.10.ADB	SK50	35	10	160	AD/B	•
SK50.160.WE.12.ADB	SK50	42	12	160	AD/B	•
SK50.160.WE.14.ADB	SK50	44	14	160	AD/B	•
SK50.160.WE.16.ADB	SK50	48	16	160	AD/B	•
SK50.160.WE.18.ADB	SK50	50	18	160	AD/B	•
SK50.160.WE.20.ADB	SK50	52	20	160	AD/B	•
SK50.160.WE.25.ADB	SK50	65	25	160	AD/B	•
SK50.160.WE.32.ADB	SK50	72	32	160	AD/B	•
SK50.160.WE.40.ADB	SK50	80	40	160	AD/B	•
SK50.200.WE.06.ADB	SK50	25	6	200	AD/B	•
SK50.200.WE.08.ADB	SK50	28	8	200	AD/B	•
SK50.200.WE.10.ADB	SK50	35	10	200	AD/B	•
SK50.200.WE.12.ADB	SK50	42	12	200	AD/B	•
SK50.200.WE.14.ADB	SK50	44	14	200	AD/B	•
SK50.200.WE.16.ADB	SK50	48	16	200	AD/B	•
SK50.200.WE.18.ADB	SK50	50	18	200	AD/B	•
SK50.200.WE.20.ADB	SK50	52	20	200	AD/B	•
SK50.200.WE.25.ADB	SK50	65	25	200	AD/B	•
SK50.200.WE.32.ADB	SK50	72	32	200	AD/B	•
SK50.200.WE.40.ADB	SK50	80	40	200	AD/B	•

od průměr d = 25 se dvěma upínacími šrouby  
from d = 25 on two clamping screws