


# Upínač Whistle Notch pro upínací stopky


## End mill holders



### Upínač Whistle Notch DIN 6359 pro upínací stopky DIN 1835-E

For mounting straight-shank tools and included flat according to DIN 1835 form E (Whistle Notch).



Název Catalog number	Kužel Taper	d	D	A		G 2,5 25.000 min <sup>-1</sup>
SK40.50.WN.06.ADB	SK40	6	25	50	AD/B	•
SK40.50.WN.08.ADB	SK40	8	28	50	AD/B	•
SK40.50.WN.10.ADB	SK40	10	35	50	AD/B	•
SK40.50.WN.12.ADB	SK40	12	42	50	AD/B	•
SK40.50.WN.14.ADB	SK40	14	44	50	AD/B	•
SK40.63.WN.16.ADB	SK40	16	48	63	AD/B	•
SK40.63.WN.18.ADB	SK40	18	50	63	AD/B	•
SK40.63.WN.20.ADB	SK40	20	52	63	AD/B	•
SK40.100.WN.25.ADB	SK40	25	65	100	AD/B	•
SK40.100.WN.32.ADB	SK40	32	72	100	AD/B	•
SK40.120.WN.40.ADB	SK40	40	80	120	AD/B	•
SK50.63.WN.06.ADB	SK50	6	25	63	AD/B	•
SK50.63.WN.08.ADB	SK50	8	28	63	AD/B	•
SK50.63.WN.10.ADB	SK50	10	35	63	AD/B	•
SK50.63.WN.12.ADB	SK50	12	42	63	AD/B	•
SK50.63.WN.14.ADB	SK50	14	44	63	AD/B	•
SK50.63.WN.16.ADB	SK50	16	48	63	AD/B	•
SK50.63.WN.18.ADB	SK50	18	50	63	AD/B	•
SK50.63.WN.20.ADB	SK50	20	52	63	AD/B	•
SK50.80.WN.25.ADB	SK50	25	65	80	AD/B	•
SK50.100.WN.32.ADB	SK50	32	72	100	AD/B	•
SK50.100.WN.40.ADB	SK50	40	80	100	AD/B	•

od průměr d = 25 se dvěma upínacími šrouby

from d = 25 on two clamping screws